PCB wiring diagram





	Details
B-	Connect to Negative Side of Cell1.
B1	Connect to Positive Side of Cell 1.
B2	Connect to Positive Side of Cell 2.
B3	Connect to Positive Side of Cell 3.
B4	Connect to Positive Side of Cell 4.
B5	Connect to Positive Side of Cell 5.
B+	Connect to Positive Side of Cell 6
SW1	Speed control button
SW2	Power button
CON3	Connect the charger
CON2	Connect the brush motor
CON1	Connect the main motor
CON4	Connect to communication socket

			VC3923 DC V1.4				
		1					
		2					
		3					
			VC3923	FR-4	1.6		